


## DIAGNOSIS AND REPAIR OF THE LASER HANDLE



All models of bars 808nm - from 200 watts and above.



site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)

Laser performance dropped? A bad diode stack may be the cause.

Visit [www.romshi.com](http://www.romshi.com) via QR scan.