Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER EMITTER GTHM-200



In most cases, the handle malfunction is due to the fact that the outbreaks do not occur, there is no tingling either.Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Laser unit struggling? A faulty diode stack is a common issue. Learn more at www.romshi.com.