Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY DVS-1005BAI



Frequent fault of the laser handle - flashes disappear and there is no tingling. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Laser broken? Find out which part to replace - scan to visit www.romshi.com.