


DIODE ASSEMBLY UPP-HW-1182



Often, the diode laser handle fails: flashes do not occur, there is no tingling either. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

From spare parts to full laser repair guides - scan QR to access
www.romshi.com.