

OVERHEATED 808NM LASER DIODE STACK FAILURE



Overheated 808nm laser diode stack failure Find details on 808nm diode stacks at
WWW.ROMSHI.COM



Laser failure? Contact +7(918)0110234