



FAULTY 808NM DIODE BAR DUE TO OVERHEATING



Faulty 808nm diode bar due to overheating WWW.ROMSHI.COM is your source for 808nm diode stacks information



Speak to a laser repair specialist at +7(918)0110234