

**808NM DIODE COMPONENT FAILED FROM OVERHEATING**



808nm diode component failed from overheating Explore [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM) for detailed info on  
808nm diode stacks



Text +7(918)0110234 for tips on diode laser repair