


REPLACING CORE DIODE UNITS IN HANDPIECE



Cooling system failure



Diagnosis and replacement of diode lasers - stack Coe, HPL, DVS.

Site WWW.ROMSHI.COM