Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX DVS-3222BAS



One of the typical problems of the diode laser is that the impulses do not pass, the patient does not feel tingling. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Get your laser working again - scan and shop the right diode parts at romshi.com.