Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER MODULE DVS-FN-1002BAI



A common breakdown of the handle is that the laser does not emit flash and does not cause sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Laser losing power? The QR will bring you to www.romshi.com where diode stack issues are explained.