Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY SEASUNLASER 17-360



A common breakdown of the handle is that the laser does not emit flash and does not cause sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

A broken diode stack can halt your laser. Scan and see repair tips at www.romshi.com.