Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER MODULE HD-8150-500W



The malfunctions of the diode laser handle are expressed in the following: no light impulses are visible, there is no contact with the skin. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Scan the QR code to visit www.romshi.com for diode laser troubleshooting info.