## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **LASER BAR LT-01AF020800N-500W**



Often, the diode laser has a problem: the laser stops issuing impulses, there are no sensations. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

When your laser hair removal device loses effectiveness, it might be due to a diode stack failure. Scan the QR code to explore repair solutions at www.romshi.com.