## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **DIODE MATRIX DVS-L-2406BAS**



One of the typical problems of the diode laser is that the outbreaks stop and the sensation of tingling disappears. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Hair removal laser malfunctioning? The diode stack could be the culprit. Scan the QR to visit www.romshi.com for details on repairs and parts.