


LASER MODULE OE-DVS-500



Drages in the work of the diode laser handle are expressed as follows: there is a loss of flashes and sensations. The handle defect is often visually observed through the window.



Laser repair and part selection support - scan QR to access
www.romshi.com.