Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR LT-21GFF001000N



Often, the diode laser handle fails: no light impulses are visible, there is no contact with the skin. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

A malfunctioning diode stack often causes laser failures. Scan the QR to get info on repairs at www.romshi.com.