

DIODE MATRIX HRI-500H



A common breakdown of the handle is that the laser stops issuing impulses, there are no sensations. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

If laser results have dropped, your diode stack might need attention.

Use the QR code to learn more at www.romshi.com.