


LASER MODULE HMA-808-50-10



Often, the diode laser handle fails: the impulses do not pass, the patient does not feel tingling. Often the problem is determined visually through the window on the handle.



Get laser repair support and spare parts guidance at www.romshi.com by scanning the QR code.

site WWW.ROMSHI.COM