


## LASER EMITTER LST-L-3235BAS



In most cases, the handle malfunction is due to the fact that the laser stops issuing impulses, there are no sensations. The handle defect is often visually observed through the window.



site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)

Problems with your laser device? [www.romshi.com](http://www.romshi.com) offers solutions-scan the QR code to find out more.