Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK LST-L-3244BAS



Often, the diode laser has a problem: the flashes stop and the sensation of tingling disappears. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

QR leads to expert guidance on diode laser spare parts at www.romshi.com.