

LASER MODULE LST-3244AS



Often, the diode laser handle fails: the laser does not emit flash and does not cause sensations. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Struggling to find the right diode component? www.romshi.com can help - scan the QR.