


LASER BAR HD-8A50-500W



Frequent malfunction of the laser handle - impulses do not pass, the patient does not feel tingling. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Noticing poor performance from your laser hair removal machine?

Check the diode stack-scan the QR for www.romshi.com.