Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY HPL-21214-GX



The most common problem with the diode laser handle - there is a loss of flashes and sensations.Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Find replacement parts and repair help for your laser at www.romshi.com via QR.