Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY GTHM-300



In most cases, the handle malfunction is due to the fact that the impulses do not pass, the patient does not feel tingling. Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

www.romshi.com helps you fix lasers with the correct parts - scan QR to learn how.