Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY LST-3123AS



In most cases, the handle malfunction is due to the fact that light pulses are not visible, there is no contact with the skin. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Scan to discover spare parts recommendations and laser repair info at www.romshi.com.