Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK LSR-3444AS



Often, the diode laser has a problem: flashes do not occur, there is no tingling either. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

For diode laser part support, visit www.romshi.com by scanning the QR code.