Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX DS-3217AS



Frequent fault of the laser handle - flashes do not occur, there is no tingling either. The breakdown is often noticeable when examining the handle.



site WWW.ROMSHI.COM

Laser not delivering results? www.romshi.com (via QR) can help-often it's the diode stack.