## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **LASER MODULE DVS-3228AS**



One of the typical problems of the diode laser is that the loss of flashes and sensations occurs. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

Laser issues? Find repair info and spare parts at www.romshi.com with a simple QR scan.