

## LASER EMITTER DVS-344CHAS



Dot in the work of the diode laser handle is expressed as follows: the impulses do not pass, the patient does not feel tingling. Often the problem is determined visually through the window on the handle.



site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)

Diode stacks fail over time. Scan QR to find replacements and guides at [www.romshi.com](http://www.romshi.com).