Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX HD-8A30-D06L



Frequent fault of the laser handle - flashes disappear and there is no tingling.Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Malfunctioning laser hair removal? Scan QR to learn if it's the diode stack-www.romshi.com.