

## **LASER MODULE 10B-2308-0775**



Frequent malfunction of the laser handle - impulses do not pass, the patient does not feel tingling. Sometimes it can be recognized visually by looking out the window.



QR code takes you to the best diode laser parts info at [www.romshi.com](http://www.romshi.com).

site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)