

LASER EMITTER HD-8A50-D10B



In most cases, the handle malfunction is due to the fact that the outbreaks do not occur, there is no tingling either. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Scan the QR code for www.romshi.com-diode stack issues are common in laser malfunctions.