Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER MODULE DVS-1008BAI



One of the typical problems of the diode laser is that flashes disappear and there is no tingling. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Everything about diode spare parts is just a scan away - www.romshi.com.