


DIODE MATRIX HR10300



In most cases, the handle malfunction is due to the fact that the laser does not work, and the sensations disappear. The breakdown is often noticeable when examining the handle.



When laser hair removal fails, scan QR for help at www.romshi.com-usually a diode issue.