
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY HR10600



In most cases, the handle malfunction is due to the fact that the laser does not emit flash and does not cause sensations. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Want expert advice on diode components? QR takes you to www.romshi.com.