
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR HR10800



Drages in the work of the diode laser handle are expressed as follows: there is a loss of flashes and sensations. When examining through the window, you can notice a malfunction.



site WWW.ROMSHI.COM

Hair not disappearing? Scan QR to diagnose via www.romshi.com-diode stack likely culprit.