Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR FL-HVS61-6X1(3X1)-300-808



Often, the diode laser has a problem: impulses do not pass, the patient does not feel tingling.Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Trouble with laser hair removal results? Visit www.romshi.com via QR-diode stack info available.