


DIODE STACK CLE-18FH030403Q



In most cases, the handle malfunction is due to the fact that the laser does not emit flash and does not cause sensations. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

www.romshi.com offers spare part guidance for hair removal lasers
- scan to learn more.