


DIODE MATRIX DG-HL06T600-1-G-A



The most common problem with the diode laser handle - the flashes stop and the sensation of tingling disappears. Damage can be detected visually through the transparent part of the handle.



Laser not delivering results? A damaged diode stack could be the reason. Visit www.romshi.com via QR scan for assistance.