


LASER MODULE DG-HL12R1200-4-N-A



The most common problem with the diode laser handle - impulses do not pass, the patient does not feel tingling. Often the problem can be seen through the observation window.



Scan now to receive laser repair and diode part recommendations from www.romshi.com.