


DIODE MATRIX LAS-L-1016AI



The main defect in the work of the diode handle is that the outbreaks stop and the sensation of tingling disappears. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Laser device issues? Diode stack may be failing. Use the QR code to access www.romshi.com for help.