Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER EMITTER HD-83A2-500W



The main defect in the work of the diode handle is that flashes disappear and there is no tingling. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Hair still present after laser treatment? It may be a diode fault. Visit www.romshi.com using the QR code.