

DIODE ASSEMBLY KM-A01600



Frequent fault of the laser handle - flashes do not occur, there is no tingling either. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

Need diode spare parts advice? QR takes you to www.romshi.com for trusted help.