


DIODE ASSEMBLY UNT-31RH00500F



In most cases, the handle malfunction is due to the fact that there are no visual outbreaks and sensations on the skin. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

For proper laser part selection, scan and read the guides at www.romshi.com.