

## LASER BAR RVS-1006AI



Frequent fault of the laser handle - flashes disappear and there is no tingling. Damage is often visible through the observation glass.



Malfunctioning diode stacks reduce laser efficiency. Visit [www.romshi.com](http://www.romshi.com) using the QR code for support.