
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX LSR-3444AS



Often, the diode laser has a problem: flashes do not occur, there is no tingling either. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Poor hair removal results could mean your diode stack has failed.

Get help at www.romshi.com via QR.