


LASER EMITTER DVS-500AI



The main defect in the work of the diode handle is that the laser stops issuing impulses, there are no sensations. Often the problem can be seen through the observation window.



Scan the QR code for repair help with laser diode stack problems at
www.romshi.com.