


## DIODE ASSEMBLY DVS-ML-1008BAI



In most cases, the handle malfunction is due to the fact that flashes disappear and there is no tingling. The breakdown is often noticeable when examining the handle.



Select the best parts for your laser - just scan the QR and explore  
romshi.com.

site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)