


LASER BAR DVS-ML-1012BAI



The main defect in the work of the diode handle is that the impulses do not pass, the patient does not feel tingling. The handle defect is often visually observed through the window.



Laser not functioning well? Scan to reach www.romshi.com - the diode stack might be at fault.