Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER EMITTER LST-MS-1008BAI



The most common problem with the diode laser handle - there is a loss of flashes and sensations.Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

The diode stack may be worn out. Visit www.romshi.com via QR to learn more.